

30-3-E 30-3-EW 30-3UL

Grayhill, Inc. 561 Hillgrove Ave. LaGrange, Il 60525

1-11-2023

Subject: Supply Chain Constraints on Grayhill 30 Series Push Button

To All Customers, Sales Representatives and Distributors,

Due to ongoing supply chain issues and after several months of unsuccessful efforts to expedite critical material, Grayhill is suspending production on certain 30 series pushbutton product lines. The material in question is a special silver-edge lay copper strip. This critical material will not be available until late Q2 2023. Once material is available, production will resume. The target date to restart production is July 2023. Order priority will be based on order placement date with the priority given to the oldest orders. Because of this unforeseen delay, customers may cancel their orders without penalty. Notice will be provided should material become available earlier.

The following is a list of affected part numbers:

Affected Parts:

00 1 01 001		
30-01-X		
30-05-X	30-17 RED	30-2804
30-1	30-17 RED-EW	30-2805
30-15	30-1-E	30-3
30-15-E	30-1-EW	30-37
30-15-EW	30-1UL	30-37-E
30-16 BLK	30-251 BLK	30-37-EW
30-16 RED	30-251 BLK-E	30-3-E
30-16 RED-E	30-251 BLK-EW	30-3-EW
30-17 BLK	30-251 RED	30-3UL
30-17 BLK-E	30-251 RED-EW	30-37-E
30-17 RED	30-2801	30-37-EW