

Product Change Notice

Date:	June 9, 2022
Overview:	The M4Q045 series accessories are being discontinued
Reason for Change:	The M4Q045 series was discontinued in December 2022
Affected Part No(s):	Please see part number listing on page 2 of this PCN
Design Change Detail:	N/A
Effective Date:	Immediately / running change
Last Time Buy Deadline:	We have stock remaining on some of the parts for which new orders can still be accepted. As our inventory is depleted, all items will officially become obsolete.
Pricing:	Per current price list
ebm-papst employee:	Jeannine Zenobi
Attachments:	Affected part numbers (detailed on page 2 of this PCN)
Comments:	N/A

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing

Affected Part Numbers

50967-2-4039	71885-2-4053
50968-2-4039	71886-2-4053
50969-2-4039	71887-2-4053
50970-2-4039	73761-2-3634
50971-2-4039	73762-2-3634
50972-2-4039	73763-2-3634
51014-2-4053	73764-2-3634
51014-2-4053	73765-2-3634
51025-2-4053	73766-2-3634
51025-2-4053	73767-2-3634
51026-2-4053	73768-2-3634
51026-2-4053	73769-2-3634
51027-2-4053	73770-2-3634
51027-2-4053	73771-2-3634
51028-2-4053	73772-2-3634
51028-2-4053	73773-2-3634
52542-2-4037	73774-2-3634
52543-2-4037	73775-2-3634
52544-2-4037	73776-2-3634
52545-2-4037	73777-2-3634
52546-2-4037	73778-2-3634
52547-2-4037	73801-2-3634
52550-2-4037	73802-2-3634
52551-2-4037	73803-2-3634
52552-2-4037	73804-2-3634
52553-2-4037	73805-2-3634
52554-2-4037	73806-2-3634
52555-2-4037	73807-2-3634
66309-2-4039	73808-2-3634
66310-2-4039	73809-2-3634
66311-2-4039	73810-2-3634
66312-2-4039	73811-2-3634
66313-2-4039	73812-2-3634
66314-2-4039	73813-2-3634
71881-2-4053	73814-2-3634
71882-2-4053	73815-2-3634
71883-2-4053	73816-2-3634
71884-2-4053	73817-2-3634
73818-2-3634	