

Dear Valued NI Customer:

You are receiving this letter to keep you informed of changes to products that you have purchased in the past. This is being provided to you for consideration during future purchases of the same products. Detailed information on this change has been included below.

Affected Product Part Numbers

Kit Part Number	New Part Number	Old Part Number	Description
779770-01	190310M-01L	190310L-01L	CCA, NI PCI-4065
<u>779771-01</u>	195331M-01L	195331L-01L	CCA, NI PCIE-4065
<u>780011-01</u>	197159M-01L	197159L-01L	CCA, NI PXI-4065
<u>780152-01</u>	196824M-01L	196824L-01L	CCA, NI USB-4065

Change Description

Product markings have been updated to reflect the fuse change required for compliance with IEC/EN 61010-1/-2-030. The fuse rating has been changed from 250V 3.15A to 300V 4A.

Impact

There are no specification or functional changes to the product(s).

Recommended Action

You are being notified of this change to help inform your future purchases of the above product(s). No further action is required on your part.

Contact Information

Please do not reply to this email. This email account is not monitored for responses. Should you need assistance, call the NI Customer Service Center (+1-(877)-388-1952), contact your local sales representative or [contact us](#) online.

Release Date

This change is effective 10/13/2023.

If you are not the end user of this product(s), we request that you forward this notice to the end user or provide NI with information to help locate the end user.

Thank you for being an NI customer. We apologize for this inconvenience. We are committed to providing products and services that exceed customer expectations and maintaining your confidence in our products.



NI is now part of Emerson