

PRODUCT CHANGE NOTIFICATION

Product Category POWER CONNECTORS **20231113-1**

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE: 13-Nov-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☐ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Panduit has identified a packaging error within our system which created a warehouse issue. The part numbers effected are isolated within the aluminum compression connector product category:
LAB400-12-24, LAB600-12-24, LAA750-12-E, SA750-8.
The only way to solve it was to move to different part number identifiers:
LAB400-12-24F, LAB600-12-24F, LAA750-12-EF, SA750-6. We apologize for the inconvenience this has caused.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	11	13
Old product discontinuation date*	2023	12	1

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
LAB400-12-24	Direct	LAB400-12-24F
LAB600-12-24	Direct	LAB600-12-24F
LAA750-12-E	Direct	LAA750-12-EF
SA750-8	Direct	SA750-6