



8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

---

To: Littelfuse Sales, Sales Support & Valued Customers

From: Littelfuse Product Management – Industrial Business Unit

Subject: 0LD, 0LS & LPBC series part numbers obsolescence with replacements.

Document Number: LFPCN\_PG0167

Date: 22<sup>nd</sup> December 2023

This notice is to inform Littelfuse Sales, Sales Support & Customers of the obsolescence of 0LD, 0LS & LPBC series part numbers, these products are replaced by new part numbers listed below in Annexure A. Few part numbers don't have replacements.

This change is done due to the UL508A standards new requirement of listed product, product simplification and elimination of non-recyclable product lines.

This is a running change effective from October 2023.

Last time buy for the old part numbers will be 15<sup>th</sup> February 2024, at this time all remaining orders must be booked.

Please note any existing orders will be honored. All orders received during this time for old part numbers will be non-cancellable and non-returnable (NC&NR).

Thank you for your continued business. If you have any questions, or need additional information please contact your Littelfuse representative.

Sincerely,

**Prashant Kulkarni**  
Associate Product Manager  
Industrial Business Unit  
Littelfuse, Inc.  
[www.littelfuse.com](http://www.littelfuse.com)

---

## Annexure A:

| Old part number | New part number |
|-----------------|-----------------|
| OLD04023Z       | OLD25703ZXDIN   |
| OLD04042Z       | OLD45531ZX (2X) |
| OLD04043Z       | OLD45533ZX      |
| OLD25701Z       | OLD25701ZXDIN   |
| OLD2570AZXDIN   | OLD25701ZXDIN   |
| OLD2580AZXDIN   | OLD25801ZXDIN   |
| OLD29701Z       | OLD25701ZXDIN   |
| OLD29701ZXDIN   | OLD25701ZXDIN   |
| OLD29702ZXDIN   | OLD25702ZXDIN   |
| OLD29703Z       | OLD25703ZXDIN   |
| OLD29703ZXDIN   | OLD25703ZXDIN   |
| OLD2970AZXDIN   | OLD25701ZXDIN   |
| OLD335543Z      | OLD45543ZX      |
| OLD35521Z       | OLD45531ZX      |
| OLD35531Z       | OLD45531ZX      |
| OLD35551Z       | OLD45551ZX      |
| OLD35881Z       | OLD45881ZX      |
| OLD35883Z       | OLD45883ZX      |
| OLD35951Z       | OLD45951ZX      |
| OLD35952Z       | OLD45951ZX (2X) |
| OLD35953Z       | OLD45953ZX      |
| OLD35961Z       | OLD45961ZX      |
| OLD35962Z       | OLD45961ZX (2X) |
| OLD35963Z       | OLD45963ZX      |
| OLD39531Z       | OLD45531ZX      |
| OLD39532Z       | OLD45531ZX (2X) |
| OLD39533Z       | OLD45533ZX      |
| OLD39551Z       | OLD45531ZX      |
| OLD39552Z       | OLD45531ZX (2X) |
| OLD39553Z       | OLD45533ZX      |
| OLD45511Z       | OLD45851ZX      |
| OLD45512Z       | OLD45851ZX (2X) |
| OLD45513Z       | OLD45853ZX      |
| OLD45601Z       | OLD45851ZX      |
| OLD45602Z       | OLD45851ZX (2X) |
| OLD45603Z       | OLD45853ZX      |
| OLD55521Z       | No replacement  |
| OLD55522Z       | No replacement  |
| OLD55941Z       | OLD45851ZX      |
| OLD55942Z       | OLD45851ZX (2X) |
| OLD55943Z       | OLD45853ZX      |
| OLD59863Z       | No replacement  |
| OLD59923Z       | No replacement  |

| Old part number           | New part number |
|---------------------------|-----------------|
| OLS03032Z                 | OLS45821ZX (2X) |
| OLS03033Z                 | OLS45823ZX      |
| OLS21211Z                 | OLS25721ZXDIN   |
| OLS21212Z                 | OLS25722ZXDIN   |
| OLS21213Z                 | OLS25722ZXDIN   |
| OLS25521Z                 | OLS25721ZXDIN   |
| OLS25522Z                 | OLS25722ZXDIN   |
| OLS25523Z                 | OLS25723ZXDIN   |
| OLS25721Z                 | OLS25721ZXDIN   |
| OLS25722Z                 | OLS25722ZXDIN   |
| OLS2572AZXDIN             | OLS25721ZXDIN   |
| OLS29721ZXDIN             | OLS25721ZXDIN   |
| OLS29722ZXDIN             | OLS25722ZXDIN   |
| OLS29723ZXDIN             | OLS25723ZXDIN   |
| OLS2972AZXDIN             | OLS25721ZXDIN   |
| OLS31231Z                 | OLS45821ZX      |
| OLS31232Z                 | OLS45823ZX      |
| OLS31241Z                 | OLS45821ZX      |
| OLS31242Z                 | OLS45821ZX (2X) |
| OLS31243Z                 | OLS45823ZX      |
| OLS31261Z                 | OLS45821ZX      |
| OLS31262Z                 | OLS45821ZX (2X) |
| OLS31263Z                 | OLS45823ZX      |
| OLS33053Z                 | OLS43053ZX      |
| OLS33203Z                 | OLS43503ZX      |
| OLS45571Z                 | OLS43601ZX      |
| OLS45572Z                 | OLS43601ZX (2X) |
| OLS45573Z                 | OLS43603ZX      |
| LPBC02                    | OLCH1341ZX      |
| LPBC03                    | OLCH1343ZX      |
| LPBC31                    | OLCH1341ZX      |
| LPBC32                    | OLCH1341ZX      |
| LPBC33                    | OLCH1343ZX      |
| LPBC41                    | OLCH1341ZX      |
| LPBC42                    | OLCH1341ZX      |
| LPBC43                    | OLCH1343ZX      |
| Not available in old SKUs | OLD45553ZX      |

Note: New part numbers with “ZXDIN” suffix are available in SAP and with “ZX” suffix will be available till 15<sup>th</sup> February 2024.