Obsolete Part Announcement



To our Valued Partners,

We are writing to inform you of an important update regarding our product offering. After careful evaluation, we have decided to discontinue the production and sale of several products. Eliminating these products will help us align manufacturing and inventory support around the tools that are in highest demand.

Key details regarding the discontinuation:

Final Order & Shipment Date: We will not accept new orders effective May 1st for all parts listed below.

Support and Warranty: We will honor warranties for a period of **12 months** from the final shipment date.

We would like to express our sincere gratitude for your support and loyalty to our brand. We apologize for any inconvenience this discontinuation may cause.

Should you have any questions or require further assistance exploring alternative solutions, please don't hesitate to contact our customer service team at sales@excelta.com or 805-686-4686.

Thank you for your understanding and continued partnership.

Sincerely

Sean Brantl

VP of Sales & Marketing

| 10H-S-SE | 277A | 348 | AF-2-SE |
|--------------|-----------|------------|-----------|
| 17-ST-30 | 278 | 353-SS | AF-3-SE |
| 17-ST-32 | 2833 | 355-ESD | AF-4-SE |
| 17-ST-34 | 289 | 356-ESD | BLP-HOB |
| 17-ST-36 | 290EC | 368 | BLP-PL-NW |
| 17-ST-M-002 | 295 | 36A-SE | BLP-TTC |
| 17-ST-M-0025 | 298AB | 371A | DPL |
| 17-ST-M-003 | 298B-EC | 371B | DR-1 |
| 17-ST-M-004 | 298EC | 376 | DTP |
| 17-ST-M-005 | 299D-G | 390B-SA-PI | E-5510 |
| 181-10 | 29-S-SE | 391B-SA-PI | EXC-TH-BE |
| 181-22 | 306-P | 391P-SA-PI | F-2-SE |
| 181A-SE | 31B-SA-SE | 401 | F-3-SE |
| 181-SE | 31-SE | 415 | F-4-SE |
| 186 | 320A | 415-F-ET | F-5-SE |
| 187 | 320B | 416 | F-6-SE |
| 189 | 320C | 417 | F-7-SE |
| 190 | 320D | 418 | KST-DIS-1 |
| 2000RK-TEP | 320-DP | 42 | KST-DIS-2 |
| 203 | 320-DPH | 500-88-SE | M-159F-RT |
| 20A-1-SE | 320E | 50-SA-PI | M-177-SE |
| 21-SA-SE-18 | 320F | 554A-SE | MM-SA-PI |
| 220 | 320G | 5-SA-DC | NH-38-SE |
| 23D-S-SE | 320H | 6804 | PV-500-H |
| 24-4-SE | 3201 | 691D-SA-PI | R-275-C |
| 24-SA-PI | 320J | 6-PI | R-275-S |
| 24-SA-SE-PH | 330F | 73E-I | R-277-C |
| 270 | 330P | 7737-61 | R-277-S |
| 270EC | 333 | 7737-77 | SE-25 |
| 272 | 333B | 7-SA-DC | TM-105-C |
| 273 | 333C | 7-SA-ESD | 10G-SA |
| | | | |

| 274 | 333D | 900-88B-SE | 23B-SA-SE |
|------|--------|------------|-----------|
| 275 | 333E | 907-88C-SE | NH-35-SE |
| 275A | 333F | 907-89-SE | |
| 276 | 33A-SE | 909-4-SE | |





Copyright © 2024 Excelta Corporation, All rights reserved.

Our mailing address is:

Excelta Corporation 60 Easy Street Buellton, CA 93427

Phone: 805-686-4686

