

<b>Product Name:</b>	HPL584		
	SD CARD READER		
<b>Product Manager:</b>	Wang , Jimmy		
<b>Subject:</b>	Notification of Change with Immediate Effectivity		
<b>Distribution:</b>	Affected customers		
<b>Type of Change:</b>	Documentation Change		
<b>Change Description:</b>	2D Drawing update to Rev L, adding the lubricating oil option ( L8030 and L8005).		
<b>Reason for Change:</b>	Lubricating oil L8030 and L8005 is also used for production. Information missing on 2D drawing being updated.		
<b>Affected Parts:</b>	10067847*, see affected PN list		
<b>Effective Date of Change:</b>	July,31 2023		
<b>Last Time Buy Date:</b>			
<b>Earliest Disty Return Date:</b>			
<b>Last Time Shipment Date</b>			
<b>Datasheet Attached?</b>	Yes		
<b>Qual/Test Data Attached?</b>	Yes		
<b>Samples Availability Date:</b>	31 July ,2023		
<b>Available Alternatives?</b>			
<b>Questions?</b>	<i>Contact your local ACS Representative, or Product Manager</i>		
	<i>Wang , Jimmy / Product Manager</i>		
	<i>Jimmy.Wang@fci.com</i>		

**Note:**

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .