



Product / Process Change Notification (PCN)

PCN ID#: 197

Title: Supplier relocation

Change: Permanent

Honeywell Contact

Name: Dzul, Jorge

E-mail: Jorge.Dzul@Honeywell.com

Title: Sr Quality Engineer

Product Information

Affected parts and revisions:

1CPSA2A 1CPSA6A 1CPSA2 1CPSA1B 1CPSA3 1CPSA1 1CPSC4 1CPSC2A 2CPSA1A1 2CCPA1A1B2B
2CCPA1A3B1A 1CPSA1A 1CPSC2 2CPSA2A1A 2CCPA1B1B2B 1CPSA2B 2CCPA1A1A1A 1CPSA3A 2CPSA2A1B
2CPSA1A1B 2CPSC1A1 2CPSA1B1A 2CPSA1A4 2CPSA2A1 DTE6-2RN BZE6-2RQ2 BZE6-2RQ62 BZ-2RQ68 BZE6-
7RNT BZE6-2RN234 BZE6-2RN34 BZE6-2RN-F6 BZE6-7RN51 BZE6-3RN2151 BAF1-3RNX1 BZV6-RNX1 6PA1
BZE6-RQ2X2 BZE6-RN2X1 BZE6-2RN-F1 BZE6-2RN-F3 BZE6-2RN191-S BZE6-3YNT BZE6-RQ81X2 1PA109 BZE6-
2RN-F1=DT BZV6-2RQ2 DTE6-2RN-M BAF1-3CN18X1 BZV6-2RQ62 BZE6-RNX1 BZE6-3YNP BZE6-RQ8X4 1PA15
BZE6-2RN18 BZV6-2RN2 8LS1 BZE6-2RN BZE6-2RN72 BFL1-AW1 BZE6-2RN80 BAF1-2RN18-RH BZE6-2RN2
BZV6-7RN BZG1-2RN2 BAF1-2RN2-LH BZF1-2RN-RH BZ-2RN7T BAF1-2RN2-RH DTF2-2RN-RH BZF2-3YN-RH
BFL1-AW4-D BFL1-AW2 BZV6-2RN 9PA58 BAF1-2RN-LH 8LS125 BZF1-2RN-LH EXA-N BZE6-RN DTF2-2RN-LH
BZG1-2RN 208LS1 BZE6-2RN28 EXH-N BZE6-2RN184 BAF1-2RN-RH 8LS152 BZE6-2AN EX-N15 DTF2-2RN2-LH
BZE6-2RN7 BZE6-2RN81 BZE6-2RN-S 208LS125 8PA12-EX GLEB24C GLCA01C GLEA24C GLDC01D GLCA01E7B
GLCB07E7B-F019 GLCB01B GLCB01C GLDB01D GLDB01E7B GLEA01B GLCC06C GLDB01C GLDB36C-6 GLCA01B
GLDA01B GLCC01C GLDA01C GLEA24E7B GLCB01D GLDC06C GLDB01B GLCB03C GLDA01D GLDB33C-6
GLDB36C GLEB24B GLDA01E7B GLCB07E7B GLCA01D GLEB01D GLDB01A1B3 GLCA01A1B GLCA01A2A
GLDA01A2A GLCB07A1B-3 GLCA01A1B-3 GLCB01A4J GLDB01A2A GLDA01A4J GLCB06A1B-4 GLCB01A5B
GLCB01A1B GLEA24A1B GLEB24A1B GLDA01A1B GLCA01A2B GLCC03A2B GLCA01A4J GLCB01A2B GLDB01A2B
GLEA01A2B GLCA01A1A GLCB03A1B GLCB01A1A GLCC01A1B GLDC01A2B GLEB01A5B GLCB07A1B-3-F057
GLEA01A5A GLCB06A1B-3 GLEB01A1B GLEB07A1B GLAA01E7B GLZ1AE7B GLAA01E7D GLBA02E7B GLBC02E7B
GLAB01E7B GLAC01E7B 1LS1-L-SIG 201LS1 1LS3 1LS91 1LS1-L 201LS3 1LS1 1LS58 11LS1 1LS312-L 1LS2 9PA15
1LS19 1LS3-L 301LS8 1LS172 301LS2 1LS195 7LS1 1LS9-L 1LS9 201LS19 1LS2-L 3LS1 203LS1 4LS1 LSR1A LSH4L-
1B LSYHC3K LSH1A LSXR4L LSZ7H1A LSR3K LSR6B LSZ1H LSZ1R LSZ7R1A LSH3K LSH6B LSXR3K LSXH4L LSXH3K
LSH4L LSYRC3KP-FP LS2H3K LSH1E LSYRC1A LSR1A-4N LSYRC5KQ-FP LSYRB6B BXR3K LSYRC5KP-FP LSZ1N
BX4N4L LSXN4L LSN1A LSZ21N LSXN3K LSYNB4L BXN4L LSN6B LSN7L LSYNB3K LSN1A-3D LSN3K LSXN7L
LSZ7N1A BX4N3K LSF1A LS2YEB4K LSE1A LSE6C5 LSYFC7L4 LSXF3K LSF3K5 LSF7L LSYFB1A LSQYFC3K223
LSXE3K LSXE4L LSZ1F LSF7L3 LSQYFB1A328 LSE3K LSYWB1A LSF3K LS2E4K LSXZ1F LSYEC3KP-FP LSZ1E LSE1A3
LSE2B LSW3K LSF5A LSF2C LSQYFB1A344 LSZ1T LST1H LSXA4L-1A LSM7N LSA1A LSM6D LSZ1A LSZ7M6D
LSYAC3KQ-FP LSXA3K LSA4L LSYAC1E LSM2D LSA1A-2B LSA5A LSXA4L LSQ051 LSQYUB3KC319 LSP4L LSA3K
LS2A4L LSA6B BXP4L LSA2B-1B 51ML1 LSA1A-1B LSZ7A5A LSYAC1A LSZ7A1A LSYAC3KP-FP LSA2B LSYMB7N3
LSYMB2D 51ML94 LSXA4L-2C LS4A2B 51ML2-E1 LSQYMB2D324 LSQYMB2D333 LSA3K=ICI LSYMB6D LSA1A-2A
LSZ7A6B BXM4N LS2M4N LSA1A3 LSZ7A1E LS2A4LX-FP LSA3K-1B LSXA7S2-1C LSA7L-1D LSXA4K LSM4N LSP3K
LSU1A LSXM4N LSYPB1A LSYAC1ADD-1B LSXM4U LSA1A-1A LSZ1AC LSXA4L2-1C LSQ038 LS2YAB4K LSU1E
LSA1A-1D LSYUB1A LSYMB4N LSYAC1ADD LSU1A-1B LSXA4L-1C LSYAC1A-2D

Does the part number change? False

Type of Change:

OtherRelocation

Change Description:

Supplier moved their equipment used to manufacture LS10013SC, LS20383, LS20377, GL30037SC, GL45003SC, GL30038SC, LS10636SC, DD10955SC, DD10021, LS20347, LS20872, CP20010, LS20384, LS20557 to another site; no form, fit, or function is affected to the current components manufactured by them.

Reason for change:

As part of improvement, whole infrastructure as machine, tool, is moving to another supplier sites, just relocating the production areas. Nothing is changing, they are just extending their operations.

Justification for change:

Plant is optimizing the space/areas, and this relocation was considered as part of. nothing of the original layout will be change or modify

Product Identification to distinguish the change:

date code 2335

Samples (If required): Not applicable

Change Implementation Date: 2023-09-01

Honeywell is committed to providing you with a superior level of customer service. Please e- mail to contact listed above for additional information regarding this communication.

G-AST-FRM-QA.2

EFFECTIVE DATE: 3-29-22

REVISION: 0