



Customer Information Notification

2024040271 : PF8xxx New Products with NXP ATTJ Assembly Site Sourcing and Dimple Wettable Flank QFN

Note: This notice is NXP Company Proprietary.

Issue Date: Nov 02, 2024 **Effective Date:** Nov 03, 2024

Here is your personalized communication about an NXP notification.
For detailed information we invite you to view this notification online

Management summary

New PF8xxx product offerings with assembly sourced from NXP ATTJ Tianjin China, including dimple wettable flank QFN, for customer supply assurance.

Change Category

☐ Wafer Fab Process	☐ Assembly Process	☐ Product Marking	☐ Test Process	☐ Design
☐ Wafer Fab Materials	☒ Assembly Materials	☐ Mechanical Specification	☐ Test Equipment	☐ Errata
☐ Wafer Fab Location	☒ Assembly Location	☐ Packing/Shipping/Labeling	☐ Test Location	☐ Electrical spec./Test coverage
☐ Firmware	☒ Other: Data Sheet Update (Technical Clarifications / Corrections)			

Notification Overview

Description

NXP Semiconductors announces the assembly site expansion with optimized QFN package for the PF8xxx Power Management IC devices associated with this notification, from current ASECL Taiwan assembly site to NXP ATTJ Tianjin China assembly site. The QFN package changes from step-cut wettable flank / non-wettable flank to dimple wettable flank version. Product data sheets are updated to document new orderable part numbers with dimple QFN and package outline drawings, along with other technical clarifications and corrections, as detailed in the data sheets revision history section.

New PF8xxx part numbers are offered for the NXP ATTJ assembled dimple QFN products.

The assembly site expansion to NXP ATTJ results in the following change summary:

- Change to dimple wettable flank QFN package from step-cut wettable flank QFN / non-wettable flank QFN package
- Change to 7mil die thickness from 5mil die thickness
- Change to PPF lead frame from Cu lead frame with Sn plating
- Change to Henkel QMI519 die attach material from Hitachi EN4900
- Change to Hitachi CEL9220HF13CW mold compound material from Sumitomo G700LA

- Change of package outline drawing to incorporate standardized NXP ATTJ QFN package
- No change to wire type or wire diameter: identical at both assembly sites (PdCu / 33 um)
- No change to PCB solder mask pattern / stencil

The assembly site expansion to NXP ATTJ was successfully qualified adhering to NXP specifications.

Current ASECL step-cut wettable flank QFN package outline drawing 98ASA01086D / SOT684-21(DD/SC) is attached to this notification and can be found at the NXP site:

[https://www.nxp.com/docs/en/package-information/SOT684-21\(DDSC\).pdf](https://www.nxp.com/docs/en/package-information/SOT684-21(DDSC).pdf)

Current ASECL non-wettable flank QFN package outline drawing 98ASA01332D / SOT684-21 is attached to this notification and can be found at the NXP site:

<https://www.nxp.com/docs/en/package-information/SOT684-21.pdf>

New ATTJ dimple QFN package outline drawing 98ASA01750D / SOT684-29(D) is attached to this notification and can be found at the NXP site: [https://www.nxp.com/docs/en/package-information/SOT684-29\(D\).pdf](https://www.nxp.com/docs/en/package-information/SOT684-29(D).pdf)

Data sheets are updated to document new orderable part numbers with dimple QFN and package outline drawings, along with other technical clarifications and corrections. The revision history included in the updated data sheets provides a detailed description of the changes.

New PF8100_PF8200 data sheet revision 12.0 is attached to this notification and can be found at the NXP site: https://www.nxp.com/docs/en/data-sheet/PF8100_PF8200.pdf

New PF8101_PF8201 data sheet revision 5.0 is attached to this notification and can be found at the NXP site: https://www.nxp.com/docs/en/data-sheet/PF8101_PF8201.pdf

New PF8121 data sheet revision 6.0 is attached to this notification and can be found at the NXP site: <https://www.nxp.com/docs/en/data-sheet/PF8121.pdf>

Please see the attached files for additional details.

Corresponding ZVEI Delta Qualification Matrix ID: SEM-PA-01, SEM-PA-04, SEM-PA-07, SEM-PA-11, SEM-PA-18, SEM-PW-03, SEM-DS-02

Reason

Qualification of NXP ATTJ Tianjin China assembly site with dimple wettable flank QFN optimization is required for customer supply assurance.

Identification of Affected Products

New part numbers are created for NXP ATTJ Tianjin assembled dimple QFN products.

Product assembly site, among other information, is reflected in the part marking trace code.

Please refer to the marking comparisons in the change summary attachment.

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact to function, reliability or quality. Updates to form and fit as described in the accompanying documentation.

Data Sheet Revision

A new data sheet will be issued

Disposition of Old Products

PF8xxx product associated with this notification will be dual sourced from ASECL Taiwan assembly site and from NXP ATTJ Tianjin China assembly site. Some products will become not recommended for new designs. Please see details in the attached product data sheets.

Additional information

Additional documents: [view online](#)

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name	Anqi Jiang
Position	Product Engineer
e-mail address	anqi.jiang@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2024 NXP Semiconductors. All rights reserved.

12NC	Orderable Part Number	Product Type	Product Description	Package Outline	Package Description	Product Status	Customer Specific Indicator	Product Line
935371822557	MC32PF8100A0ES	MC32PF8100A0ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371822528	MC32PF8100A0ESR2	MC32PF8100A0ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383505557	MC32PF8121A0EP	MC32PF8121A0EP	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383505528	MC32PF8121A0EPR2	MC32PF8121A0EPR2	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935386336557	MC32PF8121EUEP	MC32PF8121EUEP	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935386336528	MC32PF8121EUEPR2	MC32PF8121EUEPR2	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935385549557	MC32PF8121F1EP	MC32PF8121F1EP	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935385549528	MC32PF8121F1EPR2	MC32PF8121F1EPR2	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935385547557	MC32PF8121F2EP	MC32PF8121F2EP	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935385547528	MC32PF8121F2EPR2	MC32PF8121F2EPR2	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935400189557	MC32PF8121G5EP	MC32PF8121G5EP	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935400189528	MC32PF8121G5EPR2	MC32PF8121G5EPR2	PF8121	H(V)QFN56	SOT684-21	RFS	No	BLC4
935354255557	MC33PF8100A0ES	MC33PF8100A0ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935354255528	MC33PF8100A0ESR2	MC33PF8100A0ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935375822557	MC33PF8100CCES	MC33PF8100CCES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935375822528	MC33PF8100CCESR2	MC33PF8100CCESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935375839557	MC33PF8100CFES	MC33PF8100CFES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935375839528	MC33PF8100CFESR2	MC33PF8100CFESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382407557	MC33PF8100CHES	MC33PF8100CHES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382407528	MC33PF8100CHESR2	MC33PF8100CHESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935385412557	MC33PF8100EAES	MC33PF8100EAES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935385412528	MC33PF8100EAESR2	MC33PF8100EAESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384542557	MC33PF8100EPES	MC33PF8100EPES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384542528	MC33PF8100EPESR2	MC33PF8100EPESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384736557	MC33PF8100EQES	MC33PF8100EQES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384736528	MC33PF8100EQESR2	MC33PF8100EQESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384516557	MC33PF8100ERES	MC33PF8100ERES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384516528	MC33PF8100ERESR2	MC33PF8100ERESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935387936557	MC33PF8100F3ES	MC33PF8100F3ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935387936528	MC33PF8100F3ESR2	MC33PF8100F3ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935392269557	MC33PF8100FJES	MC33PF8100FJES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935392269528	MC33PF8100FJESR2	MC33PF8100FJESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935368343557	MC33PF8101A0ES	MC33PF8101A0ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935368343528	MC33PF8101A0ESR2	MC33PF8101A0ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935354251557	MC33PF8200A0ES	MC33PF8200A0ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935354251528	MC33PF8200A0ESR2	MC33PF8200A0ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382504557	MC33PF8200CKES	MC33PF8200CKES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382504528	MC33PF8200CKESR2	MC33PF8200CKESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382409557	MC33PF8200D2ES	MC33PF8200D2ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382409528	MC33PF8200D2ESR2	MC33PF8200D2ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382424557	MC33PF8200DBES	MC33PF8200DBES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382424528	MC33PF8200DBESR2	MC33PF8200DBESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935376115557	MC33PF8200DEES	MC33PF8200DEES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935376115697	MC33PF8200DEESR2	MC33PF8200DEESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935376117557	MC33PF8200DFES	MC33PF8200DFES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935376117697	MC33PF8200DFESR2	MC33PF8200DFESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382397557	MC33PF8200DHES	MC33PF8200DHES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935382397528	MC33PF8200DHESR2	MC33PF8200DHESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935383341557	MC33PF8200DMES	MC33PF8200DMES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383341528	MC33PF8200DMESR2	MC33PF8200DMESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383343557	MC33PF8200DNES	MC33PF8200DNES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383343528	MC33PF8200DNESR2	MC33PF8200DNESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935385416557	MC33PF8200EMES	MC33PF8200EMES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935385416528	MC33PF8200EMESR2	MC33PF8200EMESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384743557	MC33PF8200ESES	MC33PF8200ESES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384743528	MC33PF8200ESESR2	MC33PF8200ESESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384741557	MC33PF8200ETES	MC33PF8200ETES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935384741528	MC33PF8200ETESR2	MC33PF8200ETESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935368347557	MC33PF8201A0ES	MC33PF8201A0ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935368347528	MC33PF8201A0ESR2	MC33PF8201A0ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	RFS	No	BLC4
935383793557	MC34PF8100A0EP	MC34PF8100A0EP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383793528	MC34PF8100A0EPR2	MC34PF8100A0EPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383795557	MC34PF8100CCPE	MC34PF8100CCPE	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383795528	MC34PF8100CCPEPR2	MC34PF8100CCPEPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383802557	MC34PF8100CFEP	MC34PF8100CFEP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383802528	MC34PF8100CFEPR2	MC34PF8100CFEPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383913557	MC34PF8100CHEP	MC34PF8100CHEP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383913528	MC34PF8100CHEPR2	MC34PF8100CHEPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935384684557	MC34PF8100EPEP	MC34PF8100EPEP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935384684528	MC34PF8100EPEPR2	MC34PF8100EPEPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935384682557	MC34PF8100EQEP	MC34PF8100EQEP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935384682528	MC34PF8100EQEPR2	MC34PF8100EQEPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935384679557	MC34PF8100EREP	MC34PF8100EREP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935384679528	MC34PF8100EREPR2	MC34PF8100EREPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935386358557	MC34PF8100F3EP	MC34PF8100F3EP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935386358528	MC34PF8100F3EPR2	MC34PF8100F3EPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935400487557	MC34PF8100FJEP	MC34PF8100FJEP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935400487528	MC34PF8100FJEPR2	MC34PF8100FJEPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383915557	MC34PF8101A0EP	MC34PF8101A0EP	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935383915528	MC34PF8101A0EPR2	MC34PF8101A0EPR2	PF8100	H(V)QFN56	SOT684-21	RFS	No	BLC4
935371831557	MC34PF8101A0ES	MC34PF8101A0ES	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371831528	MC34PF8101A0ESR2	MC34PF8101A0ESR2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372061699	PC32PF8100A0ES	PC32PF8100A0ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372061697	PC32PF8100A0ESR2	PC32PF8100A0ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383825699	PC32PF8121A0EP	PC32PF8121A0EP	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383825697	PC32PF8121A0EPR2	PC32PF8121A0EPR2	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383824699	PC32PF8121E8EP	PC32PF8121E8EP	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383824697	PC32PF8121E8EPR2	PC32PF8121E8EPR2	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383838699	PC32PF8121EEEP	PC32PF8121EEEP	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4

935383838697	PC32PF8121EEEEPR2	PC32PF8121EEEEPR2	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383832699	PC32PF8121EKEP	PC32PF8121EKEP	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383832697	PC32PF8121EKEPR2	PC32PF8121EKEPR2	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935390118699	PC32PF8121F9EP	PC32PF8121F9EP	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935390118697	PC32PF8121F9EP2	PC32PF8121F9EP2	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935400183699	PC32PF8121G5EP	PC32PF8121G5EP	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935400183697	PC32PF8121G5EP2	PC32PF8121G5EP2	PF8121	H(V)QFN56	SOT684-21	ASM	No	BLC4
935354257557	PC33PF8100A0ES	PC33PF8100A0ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935354257528	PC33PF8100A0ESR2	PC33PF8100A0ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373702557	PC33PF8100C1ES	PC33PF8100C1ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373702528	PC33PF8100C1ESR2	PC33PF8100C1ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382896699	PC33PF8100C9ES	PC33PF8100C9ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382896697	PC33PF8100C9ESR2	PC33PF8100C9ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382982699	PC33PF8100CAES	PC33PF8100CAES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382982697	PC33PF8100CAESR2	PC33PF8100CAESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382979699	PC33PF8100CBES	PC33PF8100CBES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382979697	PC33PF8100CBESR2	PC33PF8100CBESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371463699	PC33PF8100CCES	PC33PF8100CCES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371463697	PC33PF8100CCESR2	PC33PF8100CCESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372025699	PC33PF8100CDES	PC33PF8100CDES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372025697	PC33PF8100CDES2	PC33PF8100CDES2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372027699	PC33PF8100CEES	PC33PF8100CEES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372027697	PC33PF8100CEESR2	PC33PF8100CEESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371818699	PC33PF8100CFES	PC33PF8100CFES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371818697	PC33PF8100CFESR2	PC33PF8100CFESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382971699	PC33PF8100CGES	PC33PF8100CGES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382971697	PC33PF8100CGESR2	PC33PF8100CGESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382968699	PC33PF8100CHES	PC33PF8100CHES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382968697	PC33PF8100CHESR2	PC33PF8100CHESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372093699	PC33PF8100CKES	PC33PF8100CKES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372093697	PC33PF8100CKESR2	PC33PF8100CKESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935377185699	PC33PF8100CLEES	PC33PF8100CLEES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935377185697	PC33PF8100CLESR2	PC33PF8100CLESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935369408557	PC33PF8100CMES	PC33PF8100CMES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935369408528	PC33PF8100CMESR2	PC33PF8100CMESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378464699	PC33PF8100CRES	PC33PF8100CRES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378464697	PC33PF8100CRESR2	PC33PF8100CRESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371951699	PC33PF8100CSES	PC33PF8100CSES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371951697	PC33PF8100CSES2	PC33PF8100CSES2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935377467699	PC33PF8100CTES	PC33PF8100CTES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935377467697	PC33PF8100CTESR2	PC33PF8100CTESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382977699	PC33PF8100CUES	PC33PF8100CUES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382977697	PC33PF8100CUESR2	PC33PF8100CUESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382975699	PC33PF8100CWES	PC33PF8100CWES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382975697	PC33PF8100CWESR2	PC33PF8100CWESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374601699	PC33PF8100CXES	PC33PF8100CXES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374601697	PC33PF8100CXESR2	PC33PF8100CXESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382973699	PC33PF8100CYES	PC33PF8100CYES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382973697	PC33PF8100CYESR2	PC33PF8100CYESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935381085699	PC33PF8100CZES	PC33PF8100CZES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935381085697	PC33PF8100CZESR2	PC33PF8100CZESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935375619699	PC33PF8100D1ES	PC33PF8100D1ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935375619697	PC33PF8100D1ESR2	PC33PF8100D1ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373704557	PC33PF8100D3ES	PC33PF8100D3ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373704528	PC33PF8100D3ESR2	PC33PF8100D3ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373732557	PC33PF8100D5ES	PC33PF8100D5ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373732528	PC33PF8100D5ESR2	PC33PF8100D5ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935381989699	PC33PF8100D8ES	PC33PF8100D8ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935381989697	PC33PF8100D8ESR2	PC33PF8100D8ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935375884699	PC33PF8100DCEES	PC33PF8100DCEES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935375884697	PC33PF8100DCESR2	PC33PF8100DCESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374614699	PC33PF8100DJES	PC33PF8100DJES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374614697	PC33PF8100DJESR2	PC33PF8100DJESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374951699	PC33PF8100DKES	PC33PF8100DKES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374951697	PC33PF8100DKESR2	PC33PF8100DKESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935376415699	PC33PF8100DLES	PC33PF8100DLES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935376415697	PC33PF8100DLESR2	PC33PF8100DLESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935376422699	PC33PF8100DPES	PC33PF8100DPES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935376422697	PC33PF8100DPESR2	PC33PF8100DPESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378538699	PC33PF8100DRES	PC33PF8100DRES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378538697	PC33PF8100DRESR2	PC33PF8100DRESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378536699	PC33PF8100DUES	PC33PF8100DUES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378536697	PC33PF8100DUESR2	PC33PF8100DUESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378732699	PC33PF8100DVES	PC33PF8100DVES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378732697	PC33PF8100DVESR2	PC33PF8100DVESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378989699	PC33PF8100DWES	PC33PF8100DWES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378989697	PC33PF8100DWESR2	PC33PF8100DWESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935379243699	PC33PF8100DXES	PC33PF8100DXES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935379243697	PC33PF8100DXESR2	PC33PF8100DXESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383729699	PC33PF8100DYES	PC33PF8100DYES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383729697	PC33PF8100DYESR2	PC33PF8100DYESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935410357699	PC33PF8100EOES	PC33PF8100EOES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935410357697	PC33PF8100EOESR2	PC33PF8100EOESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935379841699	PC33PF8100E1ES	PC33PF8100E1ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935379841697	PC33PF8100E1ESR2	PC33PF8100E1ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935380591699	PC33PF8100E3ES	PC33PF8100E3ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935380591697	PC33PF8100E3ESR2	PC33PF8100E3ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935380584699	PC33PF8100E4ES	PC33PF8100E4ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935380584697	PC33PF8100E4ESR2	PC33PF8100E4ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382867699	PC33PF8100EAES	PC33PF8100EAES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4

935429624697	PC33PF8100JESR2	PC33PF8100JESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935427725699	PC33PF8100JHES	PC33PF8100JHES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935427725697	PC33PF8100JHESR2	PC33PF8100JHESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935427943699	PC33PF8100JJE5	PC33PF8100JJE5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935427943697	PC33PF8100JJE5R2	PC33PF8100JJE5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935427769699	PC33PF8100JKE5	PC33PF8100JKE5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935427769697	PC33PF8100JKE5R2	PC33PF8100JKE5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935427932699	PC33PF8100JLE5	PC33PF8100JLE5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935427932697	PC33PF8100JLE5R2	PC33PF8100JLE5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935430058699	PC33PF8100JME5	PC33PF8100JME5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935430058697	PC33PF8100JME5R2	PC33PF8100JME5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935429626699	PC33PF8100JPE5	PC33PF8100JPE5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935429626697	PC33PF8100JPE5R2	PC33PF8100JPE5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935438886699	PC33PF8100JUE5	PC33PF8100JUE5	PF8100 QFN-EP 56	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935438886697	PC33PF8100JUE5R2	PC33PF8100JUE5R2	PF8100 QFN-EP 56	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935435753699	PC33PF8100JWE5	PC33PF8100JWE5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935435753697	PC33PF8100JWE5R2	PC33PF8100JWE5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935438881699	PC33PF8100K3E5	PC33PF8100K3E5	PF8100 QFN-EP 56	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935438881697	PC33PF8100K3E5R2	PC33PF8100K3E5R2	PF8100 QFN-EP 56	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935438999699	PC33PF8100K4E5	PC33PF8100K4E5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935438999697	PC33PF8100K4E5R2	PC33PF8100K4E5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935443688699	PC33PF8100K6E5	PC33PF8100K6E5	PF8100 QFN-EP 56	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935443688697	PC33PF8100K6E5R2	PC33PF8100K6E5R2	PF8100 QFN-EP 56	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368936557	PC33PF8100Q1E5	PC33PF8100Q1E5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368936528	PC33PF8100Q1E5R2	PC33PF8100Q1E5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368979557	PC33PF8100Q2E5	PC33PF8100Q2E5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368979528	PC33PF8100Q2E5R2	PC33PF8100Q2E5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368975557	PC33PF8100Q3E5	PC33PF8100Q3E5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368975528	PC33PF8100Q3E5R2	PC33PF8100Q3E5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371948699	PC33PF8100Q5E5	PC33PF8100Q5E5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371948697	PC33PF8100Q5E5R2	PC33PF8100Q5E5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368345557	PC33PF8101A0E5	PC33PF8101A0E5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368345528	PC33PF8101A0E5R2	PC33PF8101A0E5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378469557	PC33PF8101D5E5	PC33PF8101D5E5	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378469528	PC33PF8101D5E5R2	PC33PF8101D5E5R2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378688557	PC33PF8101DTES	PC33PF8101DTES	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378688528	PC33PF8101DTESR2	PC33PF8101DTESR2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935380604699	PC33PF8101E2E5	PC33PF8101E2E5	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935380604697	PC33PF8101E2E5R2	PC33PF8101E2E5R2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382393699	PC33PF8101E7E5	PC33PF8101E7E5	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382393697	PC33PF8101E7E5R2	PC33PF8101E7E5R2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383352557	PC33PF8101ECES	PC33PF8101ECES	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383352528	PC33PF8101ECESR2	PC33PF8101ECESR2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383701699	PC33PF8101EHES	PC33PF8101EHES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383701697	PC33PF8101EHESR2	PC33PF8101EHESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935386569699	PC33PF8101EZES	PC33PF8101EZES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935386569697	PC33PF8101EZESR2	PC33PF8101EZESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935406229699	PC33PF8101FKES	PC33PF8101FKES	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935406229697	PC33PF8101FKESR2	PC33PF8101FKESR2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935396773699	PC33PF8101FUES	PC33PF8101FUES	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935396773697	PC33PF8101FUESR2	PC33PF8101FUESR2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935420274699	PC33PF8101J7E5	PC33PF8101J7E5	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935420274697	PC33PF8101J7E5R2	PC33PF8101J7E5R2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935440383699	PC33PF8101JTES	PC33PF8101JTES	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935440383697	PC33PF8101JTESR2	PC33PF8101JTESR2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935354253557	PC33PF8200A0E5	PC33PF8200A0E5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935354253528	PC33PF8200A0E5R2	PC33PF8200A0E5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374883699	PC33PF8200CCES	PC33PF8200CCES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374883697	PC33PF8200CCESR2	PC33PF8200CCESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378676699	PC33PF8200CLE5	PC33PF8200CLE5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378676697	PC33PF8200CLE5R2	PC33PF8200CLE5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372159699	PC33PF8200CQES	PC33PF8200CQES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372159697	PC33PF8200CQESR2	PC33PF8200CQESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378707699	PC33PF8200CRE5	PC33PF8200CRE5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378707697	PC33PF8200CRE5R2	PC33PF8200CRE5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378312699	PC33PF8200CXES	PC33PF8200CXES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935378312697	PC33PF8200CXESR2	PC33PF8200CXESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935379679699	PC33PF8200D2E5	PC33PF8200D2E5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935379679697	PC33PF8200D2E5R2	PC33PF8200D2E5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372344699	PC33PF8200D6E5	PC33PF8200D6E5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935372344697	PC33PF8200D6E5R2	PC33PF8200D6E5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373258699	PC33PF8200D9E5	PC33PF8200D9E5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373258697	PC33PF8200D9E5R2	PC33PF8200D9E5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373027699	PC33PF8200DAE5	PC33PF8200DAE5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373027697	PC33PF8200DAE5R2	PC33PF8200DAE5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373029699	PC33PF8200DBE5	PC33PF8200DBE5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935373029697	PC33PF8200DBE5R2	PC33PF8200DBE5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935375942699	PC33PF8200DDE5	PC33PF8200DDE5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935375942697	PC33PF8200DDE5R2	PC33PF8200DDE5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374953699	PC33PF8200DEE5	PC33PF8200DEE5	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935374953697	PC33PF8200DEE5R2	PC33PF8200DEE5R2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383884699	PC33PF8200DFE5	PC33PF8200DFE5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383884697	PC33PF8200DFE5R2	PC33PF8200DFE5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383834699	PC33PF8200DGE5	PC33PF8200DGE5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383834697	PC33PF8200DGE5R2	PC33PF8200DGE5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383813699	PC33PF8200DHE5	PC33PF8200DHE5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383813697	PC33PF8200DHE5R2	PC33PF8200DHE5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935376419699	PC33PF8200DME5	PC33PF8200DME5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935376419697	PC33PF8200DME5R2	PC33PF8200DME5R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935376417699	PC33PF8200DNE5	PC33PF8200DNE5	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4

935376417697	PC33PF8200DNESR2	PC33PF8200DNESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935380275699	PC33PF8200DXES	PC33PF8200DXES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935380275697	PC33PF8200DXESR2	PC33PF8200DXESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935379968699	PC33PF8200DZES	PC33PF8200DZES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935379968697	PC33PF8200DZESR2	PC33PF8200DZESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935381644699	PC33PF8200E5ES	PC33PF8200E5ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935381644697	PC33PF8200E5ESR2	PC33PF8200E5ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382984699	PC33PF8200E9ES	PC33PF8200E9ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382984697	PC33PF8200E9ESR2	PC33PF8200E9ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382986699	PC33PF8200EBES	PC33PF8200EBES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935382986697	PC33PF8200EBESR2	PC33PF8200EBESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383703699	PC33PF8200EDES	PC33PF8200EDES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383703697	PC33PF8200EDES R2	PC33PF8200EDES R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383705699	PC33PF8200EFES	PC33PF8200EFES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383705697	PC33PF8200EFESR2	PC33PF8200EFESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383707699	PC33PF8200EGES	PC33PF8200EGES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383707697	PC33PF8200EGESR2	PC33PF8200EGESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935384895699	PC33PF8200E5ES	PC33PF8200E5ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935384895697	PC33PF8200E5ESR2	PC33PF8200E5ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935384734699	PC33PF8200ETES	PC33PF8200ETES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935384734697	PC33PF8200ETESR2	PC33PF8200ETESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935390125699	PC33PF8200F7ES	PC33PF8200F7ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935390125697	PC33PF8200F7ESR2	PC33PF8200F7ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935389235699	PC33PF8200FAES	PC33PF8200FAES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935389235697	PC33PF8200FAESR2	PC33PF8200FAESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935396762699	PC33PF8200FMES	PC33PF8200FMES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935396762697	PC33PF8200FMESR2	PC33PF8200FMESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935395155699	PC33PF8200FTES	PC33PF8200FTES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935395155697	PC33PF8200FTESR2	PC33PF8200FTESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935406698699	PC33PF8200G0ES	PC33PF8200G0ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935406698697	PC33PF8200G0ESR2	PC33PF8200G0ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935399482699	PC33PF8200G4ES	PC33PF8200G4ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935399482697	PC33PF8200G4ESR2	PC33PF8200G4ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935400185699	PC33PF8200G6ES	PC33PF8200G6ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935400185697	PC33PF8200G6ESR2	PC33PF8200G6ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935399484699	PC33PF8200G7ES	PC33PF8200G7ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935399484697	PC33PF8200G7ESR2	PC33PF8200G7ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935403893699	PC33PF8200GAES	PC33PF8200GAES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935403893697	PC33PF8200GAESR2	PC33PF8200GAESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935418452699	PC33PF8200HZES	PC33PF8200HZES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935418452697	PC33PF8200HZESR2	PC33PF8200HZESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935420206699	PC33PF8200J1ES	PC33PF8200J1ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935420206697	PC33PF8200J1ESR2	PC33PF8200J1ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935420208699	PC33PF8200J4ES	PC33PF8200J4ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935420208697	PC33PF8200J4ESR2	PC33PF8200J4ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935420211699	PC33PF8200J5ES	PC33PF8200J5ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935420211697	PC33PF8200J5ESR2	PC33PF8200J5ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935426721699	PC33PF8200JDES	PC33PF8200JDES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935426721697	PC33PF8200JDES R2	PC33PF8200JDES R2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935429791699	PC33PF8200JEEES	PC33PF8200JEEES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935429791697	PC33PF8200JEEESR2	PC33PF8200JEEESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935429678699	PC33PF8200JFES	PC33PF8200JFES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935429678697	PC33PF8200JFESR2	PC33PF8200JFESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935430756699	PC33PF8200JGES	PC33PF8200JGES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935430756697	PC33PF8200JGESR2	PC33PF8200JGESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935428722699	PC33PF8200JNES	PC33PF8200JNES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935428722697	PC33PF8200JNESR2	PC33PF8200JNESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935435755699	PC33PF8200JVES	PC33PF8200JVES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935435755697	PC33PF8200JVESR2	PC33PF8200JVESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935436163699	PC33PF8200JXES	PC33PF8200JXES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935436163697	PC33PF8200JXESR2	PC33PF8200JXESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935439116699	PC33PF8200JZES	PC33PF8200JZES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935439116697	PC33PF8200JZESR2	PC33PF8200JZESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935442946699	PC33PF8200K7ES	PC33PF8200K7ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935442946697	PC33PF8200K7ESR2	PC33PF8200K7ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935461322699	PC33PF8200KCES	PC33PF8200KCES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935461322697	PC33PF8200KCESR2	PC33PF8200KCESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935456337699	PC33PF8200KEES	PC33PF8200KEES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935456337697	PC33PF8200KEESR2	PC33PF8200KEESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368938557	PC33PF8200T1ES	PC33PF8200T1ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368938528	PC33PF8200T1ESR2	PC33PF8200T1ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368977557	PC33PF8200T2ES	PC33PF8200T2ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368977528	PC33PF8200T2ESR2	PC33PF8200T2ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371953699	PC33PF8200T6ES	PC33PF8200T6ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371953697	PC33PF8200T6ESR2	PC33PF8200T6ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368349557	PC33PF8201A0ES	PC33PF8201A0ES	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935368349528	PC33PF8201A0ESR2	PC33PF8201A0ESR2	PF8200	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383719699	PC34PF8100A0EP	PC34PF8100A0EP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383719697	PC34PF8100A0EPR2	PC34PF8100A0EPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935371999699	PC34PF8100A0ES	PC34PF8100A0ES	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371999697	PC34PF8100A0ESR2	PC34PF8100A0ESR2	PF8100	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935383732699	PC34PF8100CCPE	PC34PF8100CCPE	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383732697	PC34PF8100CCPEPR2	PC34PF8100CCPEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383736699	PC34PF8100CDEP	PC34PF8100CDEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383736697	PC34PF8100CDEPR2	PC34PF8100CDEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383738699	PC34PF8100CEEP	PC34PF8100CEEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383738697	PC34PF8100CEEPR2	PC34PF8100CEEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383743699	PC34PF8100CFEP	PC34PF8100CFEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383743697	PC34PF8100CFEPR2	PC34PF8100CFEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383745699	PC34PF8100CGEP	PC34PF8100CGEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4

935383745697	PC34PF8100CGEPR2	PC34PF8100CGEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383741699	PC34PF8100CHEP	PC34PF8100CHEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383741697	PC34PF8100CHEPR2	PC34PF8100CHEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935384691699	PC34PF8100EPEP	PC34PF8100EPEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935384691697	PC34PF8100EPEPR2	PC34PF8100EPEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935384738699	PC34PF8100EQEP	PC34PF8100EQEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935384738697	PC34PF8100EQEPR2	PC34PF8100EQEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935384688699	PC34PF8100EREP	PC34PF8100EREP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935384688697	PC34PF8100EREPR2	PC34PF8100EREPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935389814699	PC34PF8100F8EP	PC34PF8100F8EP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935389814697	PC34PF8100F8EPR2	PC34PF8100F8EPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935399496699	PC34PF8100FWEP	PC34PF8100FWEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935399496697	PC34PF8100FWEPR2	PC34PF8100FWEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935437723699	PC34PF8100K2EP	PC34PF8100K2EP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935437723697	PC34PF8100K2EPR2	PC34PF8100K2EPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935455448699	PC34PF8100KDEP	PC34PF8100KDEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935455448697	PC34PF8100KDEPR2	PC34PF8100KDEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935455444699	PC34PF8100KFEP	PC34PF8100KFEP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935455444697	PC34PF8100KFEPR2	PC34PF8100KFEPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383791699	PC34PF8101A0EP	PC34PF8101A0EP	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935383791697	PC34PF8101A0EPR2	PC34PF8101A0EPR2	PF8100	H(V)QFN56	SOT684-21	ASM	No	BLC4
935371602699	PC34PF8101A0ES	PC34PF8101A0ES	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371602697	PC34PF8101A0ESR2	PC34PF8101A0ESR2	PF8101	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371604699	PC34PF8201A0ES	PC34PF8201A0ES	PF8201	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4
935371604697	PC34PF8201A0ESR2	PC34PF8201A0ESR2	PF8201	H(V)QFN56WF	SOT684-21(DD/SC)	ASM	No	BLC4